



CONSTRUCTION

HARTFORD JT 1

JUNE 26, 2025

CENTRAL

Look at the new health room in the Central office starting to take shape!




LINCOLN

The Lincoln kitchen cooler and freezer have been disassembled and removed. Also, the floors have been saw cut for the flooring repair and the new food cooler and freezer.

ROSSMAN

The toilet in this picture was removed as we enhance the bathrooms to include a wider, ADA-compliant stall for bathrooms that do not have one.



Watch our progress throughout the summer!

THANK YOU, VOTERS!

